

Successful Implementation of Steel Coating and Bridge Rehab Projects

Rex A. Costley, P.E.
Director of Maintenance
Texas Department of Transportation

Table of Contents

- 1 Pharr District Facts
- 2 QIC Facts
- 3 QIC Bridge Features
- 4 QIC Structural Repair Cleaning and Painting Successes and Lessons Learned
- 5 QIC Service Life Assessment and Rehabilitation Strategies
- 6 QIC 2013 Repairs
- 7 Reasons for QIC in Good Condition

Table of Contents

8

TxDOT's Plan Moving Forward


9

Questions

Pharr District Facts

Pharr is a Coastal District with 14 International crossings and serves as a NAFTA corridor. Currently, none of the Pharr District bridges are load rated. Thanks to ongoing maintenance efforts of our structures.

FY 2017	
Population	1,385,195
Square Miles Area	8,812
Lane Miles	6,510 (+102)
Centerline Miles	2,378
Daily Vehicle Miles	19,283,619



Pharr District Facts

On-System Bridges	
State Bridge Total	35,489
State Sufficiency Rating	88%
Pharr District Total	728
Sufficiency Rating	92%

On-System inspections occur every two years. These inspections ensure all bridges open to traffic are safe. Reports are developed along with Follow-up Action reports to correct any significant issues to maintain bridge integrity.

Heights

E Ocean Blvd

48

100

Port Isabel

Long Island

South Padre Island

Queen-Isabella-Causeway

Image © 2018 TerraMetrics
© 2018 Google

Data SIO, NOAA, U.S. Navy, NGA, GEBCO

Clark Island

Google Earth

QIC Facts

- Connects Port Isabel to South Padre Island
- Constructed between 1973 and 1974
- 2.36 miles long and 67.75' wide (2 – 12' lanes with inside and outside shoulders)
- 150 Pre-stressed Type 54 Concrete Beam Unit Spans (80')
- 1 – 750' Variable Depth Plate Girder three span continuous unit (220' – 310' – 220')
- 78' Vertical clearance and 200' horizontal clearance over Inter Coastal Waterway
- September 15, 2001 Vessel Impact – 320' of Bridge removed and replaced
- Steel coating operations – 1982, 1997, and 2010

QIC Maintenance History Costs

FY	PROJECT DESCRIPTION	PROJECT COST
1997	CATHODIC PROTECTION (BENT 19-24)	\$478,000.00
1997	REHAB/PAINT MAIN SPAN	\$618,601.71
2001	EMERGENCY REPAIRS (SPAN 29-33)	\$5,918,012.88
2003	CATHODIC PROTECTION	\$3,117,394.00
		\$445,000.00
2003	EARLY WARNING DETECTION	\$842,861.00
2003	PIER PROTECTION & FENDER SYSTEM	\$3,262,255.00
		\$2,602,800.00
2003	PIER PROTECTION & FENDER SYSTEM	\$6,589,207.38
2004	CATHODIC PROTECTION	\$1,296,103.06
2007	DOLPHIN & FENDER REPAIRS	\$1,084,750.00
2009	REPAIRS TO DECK SPAN #3	\$55,482.80
2010	REHAB/PAINT MAIN SPAN/CATH PROTECTION	\$3,940,365.06
2010	REPLACE ILLUMINATION POLES/FIXT	\$410,856.68
2010	DOLPHIN & FENDER REPAIRS	\$13,336.27
2011	DOLPHIN & FENDER REPAIRS	\$17,001.25
2012	DOLPHIN & FENDER REPAIRS	\$263,909.00
2013	STRUCTURE REPAIRS, RAIL RETROFIT, SILANE TREATMENT, BEAM END REPAIR	\$2,811,843.96
	PROJECTED TOTAL	\$33,767,780.05

Bridge Elements

Roadway Approach Port Isabel Side



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Roadway Approach South Padre Island Side



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Side View



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Type 54 Girders with Internal Concrete Diaphragm



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Multi-Column Bent

Mid and Lower Tie Beams Resting on Pile Cap Footing



750' Variable Depth Steel Girder Unit – 3 Girders



Steel Girder with Internal Diaphragms



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Existing Conditions



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Existing Conditions



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Existing Conditions



Existing Conditions



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Existing Conditions



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Maintenance Improvement

- Blast cleaning with steel grit
- All deteriorated steel areas repaired or replaced with new structural steel
- System III Zinc Clad Marine Paint System (Three Steel Coating Operations)
 - Priming
 - Intermediate Epoxy Coating
 - Appearance Coating



Contractor Operations

- Requires one lane closure – stationary
- Equipment includes: dehumidifier, dust collector, recycle unit, air compressor, job trailer, barrels of steel grit, plastic tarps and rigging



Rigging and Containment



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Rigging and Containment



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Rigging and Containment



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Paint Removal (Removing Pack Rust)



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Paint Removal (Blasting)



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Paint Removal (Blasting)



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Paint Removal (Blasting)



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER


Paint Removal (Blasting)



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Paint Removal (Blasting)



Repairs

[illegible]

County _____ Hwy _____ Design _____ Date _____
 C&J _____ IDW _____ Check _____ Date _____
 Sheet 2 of _____

Existing TS 8"x8"
 Cut Line 12"~18"
 Top Beaten R 12"x10"x 1/8" (8") Cut Line
 1/2" Gusset R
 Connection plates on Both Sides of TS.
 Cap plate 9"x7 1/2"x 1/2" to close TS (see Cap detail)
 ① Weld watertight on all sides of connection.

Option 1 Detail
 (Side View)

6"
 37" (43")
 3/8" Connection R
 2 3/8" 1/16"
 8" Notched to fit Gusset R's.
 Sloped Notch For Bend Plate Location

County _____ Hwy _____ Design _____ Date _____
 C-S-J _____ ID# _____ Check _____ Date _____
 Sheet 4 of 6

IS RING
 2mm

Cap

A

Gusset R

Notched to fit Gusset R's.

Channels
 C9x20
 $L = 77" (43")$ Both sides.

Inside Cap to close TS

Option 2 Detail

Side View

25"

25"

7/16"

8 3/8"


Cap R.
 $3 \frac{1}{2} \times 8 \frac{1}{2} \times \frac{1}{2}$

Fillet Material (Epoxy Type)


① $\frac{1}{4}"$

A-A


Repairs




Repairs



Repairs



Repairs



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Repairs



Repairs



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Repairs



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Repairs



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Repairs



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Repairs



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

4-12-11 Gussets w/ Bolts
completed ES - 8.9 Dia 18
completed WS 5.6 Dia 10

4-12-11 31 lengths complete


4-13-11 38 " "

- Ben 36 Type 1
- Ben 35 Type 2
- Ben 35 Tube Hole

- Bent 35 - G2 ES 6" cw + 4"
- Bent 35 Dia ES 2 Patch plates
- Bent 35 Dia ES - Cap 6"
- Dia 10 - G1 CW 6" + 4"
- Dia 12 - G2 CW 10"
- ES - Dia 23 G1 CW 4" + 4"
- Dia 23 OR ES CW 4" + 5"
- Dia 14 G1 ES CW 7" + 5"

Dia 7-4 G2 E3 CW 5
 Dia 4-6 G1 E3 CW 5
 Dia 4-5 G1 E3 CW 4
 Dia 6-7 G1 E3 CW 7
 Dia 6-7 G2 E3 CW 4
 Dia 7-8 G2 E3 CW 4
 Dia 8-9 Tube Hole
 Dia 4-5 Tube Hole
 Dia 2-3 ES 5 Brown p

DIA 45 GIES Tube Hole
 DIA 72 GIES clip 2"
 DIA 78 G 2 ES Tube
 DIA 89 G 2 ES Cw¹¹ Hole
 DIA 89 G 1 - ES Tube Hole
 Lashes



PLAN ~ Steel Repair Location
CONTINUOUS PLATE GIRDER UNIT

NOTES:
Clean and Paint all steel components on bridge (including but not limited to: beams, stiffeners, diaphragms, bracing, and shoe bearings) in accordance with Item 446, "Cleaning and Painting Steel."
APPROXIMATE TOTAL SURFACE AREA = 150,000 SF

Note: This sheet includes all repairs to date and is subject to change due to post blasting operations and upon further investigation of the preferred repair type by the Engineer.

- STEEL REPAIR WORK (as annotated on drawings):
- "LC" - Install 7 lateral guides at this shoe bearing. To be paid under Item 442-2005.
 - "WELD" - Perform weld repair(s) at this node. To be paid under Item 784-2002.
 - "TUBE" - Perform steel repair(s) at the end of tube(s) at this node. To be paid under Item 784-2005.
 - "HOLE" - Perform steel repair to holes at this node. To be paid under Item 784-2005.
 - "TYPE 1" - Perform steel repair(s) to tubes at this node. To be paid under Item 9000-2004.
 - "TYPE 2" - Perform steel repair(s) to tubes at this node. To be paid under Item 9000-2004.
 - "TYPE 1 OR 2 TUBE REPAIR" - Perform steel repair(s) to tubes. To be paid under Item 9000-2005.
 - "CRACKED WELDS" - Perform weld repair(s) at this node. To be paid under Item 9000-2004 or 9000-2005.
 - "DIAPHRAGM ENDS" - Perform steel repair(s) to ends of diaphragm. To be paid under Item 9000-2009.
 - "CLIP ENDS" - Perform steel repair(s) to holes at this diaphragm. To be paid under Item 9000-2010.
 - "CLIP STIFFENER" - Perform steel repair(s) to stiffener. To be paid under Item 9000-2011.
 - "SMALL HOLES" - Perform steel repair(s) to diagonal tubes. To be paid under Item 9000-2012.
- Investigation of the preferred repair type by the Engineer.

CHANGE ORDER No. _____

Sheet 1 of 1
Texas Department of Transportation
Design Division
QUEEN ISABELLA
CAUSEWAY

Plate Girder Unit
Additional Repair Details[illegible]

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER


Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER


Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Operations



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Steel Coating Successes

- Good Third Party NACE III Inspectors
- Good painting contractor
- Good structural steel repair contractor
- Excellent structural steel inspector
- Excellent Bridge Division support with respect to structural detailing, RFI's, shop drawing reviews, etc.
- Continued support from District management team allowing overruns for unforeseen conditions due to post blasting operations

Steel Coating Successes



Lessons Learned

- Strengthen notes with respect to no lane closures allowed during Texas Spring Break and Heavy Holidays
- Strengthen notes with respect to projecting compromised conditions due to post blasting operations
- Avoid metal to metal contact with respect to rigging
- Include provisions on rounding sharp edges to prevent localized paint failure and cracking
- Knowledge transfer for next generation

QIC Service Life Assessment

Condition and Service Life Assessment August 2009

- Based on the assessment findings, the Causeway is in good condition considering its age and service environment



QUEEN ISABELLA MEMORIAL CAUSEWAY Condition and Service Life Assessment

South Padre Island, Texas



Final Report
August 25, 2009
WJE No. 2008.5102.1



Prepared for:
Mr. Rex Costley
Pharr District Bridge Engineer
Texas Department of Transportation
600 W US Expressway 83
Pharr, TX 78577-1231

Prepared by:
Wiss, Janney, Elstner Associates, Inc.
TBPE Certification of Registration No. 0093
13581 Pond Springs Road Suite 107
Austin, Texas 78729
512.835.0940 tel | 512.835.6268 fax



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018


PRACTICES WE CAN NOT AFFORD TO DEFER

QIC Service Life Assessment

Strategies For Extending the Life of the Structure

1. Not employing any significant remediation efforts and only continuing with “routine” maintenance
2. Employing both remediation and routine maintenance efforts to optimize the service life relative to cost
3. Employing comprehensive remediation efforts to extend the service life of the beams and lower substructure elements to approximately that of the other elements
 - Present estimated cost for QIC Replacement is ~ \$ 125 M. (2009)
 - Service Life – bridge able to satisfy state legal load of 80,000 pounds. TxDOT’s goal is to avoid load posting of bridge (baseline).
 - No significant maintenance remedies performed for the first 20 years (1974 to 1995) other than steel coatings

QIC Service Life Assessment



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Option 1

- Repair and paint steel girders (\$4,500,000)
- Replace deteriorated anchor bolts and guard rails with a T-4 three-bolt railing system (\$627,500)
- Remove and replace deteriorated light standards (\$680,000)
- Repair and paint exposed end connections for lateral tie roads (\$117,000)
- Miscellaneous work (structural and Cathodic Protection (\$75,000)
- **COMPLETED** via BPM 6207-63-001 and CSJ 0331-04-065 (2010 to 2013)

Option 2

- Includes all items captured in Option 1 and extends the service life an additional 10 to 15 years (2033). Again, the pre-stressed beams are the controlling element. This includes the repair and repainting of the steel unit. This will be the fourth repainting effort (1983, 1995, 2010, 2020+ TBD). Total cost for this work is estimated at \$14M.
- Perform all items in Option 1 (\$6,946,600) **COMPLETED**
- Repair all existing spalls and major crack elements utilizing conventional repair techniques (\$1,203,750)
- Repair end patches at all Type 54 beams (\$600,000)
- Apply a single application of a penetrating silane sealer to all exposed surfaces of the Type 54 beams and diaphragms (\$802,500)
- **COMPLETED** above work VIA CSJ 0331-04-065 (2010-2013)

Option 3

- Includes all items captured in Option 1 and 2 with additional remediation efforts for the beams and the existing cathodic protection system on the lower substructure to yield a service life up to 40 years (2043). Again the pre-stressed beams are the controlling element. Total cost for this work is estimated at \$ 21.5 M.
- Perform all items in Option 1 and 2, except as noted below, within a one or two year time period (\$14,079,850) - **COMPLETED**
- Apply CP system (zinc alloy thermal spray) to all Type 54 beams at ends, sides, and soffits (bottoms) for a distance of 3 feet from each end in approximately six to eight years following the first silane application (\$2,000,000) (**PLANNED**)
- Apply second application of a penetrating silane sealer to beam and diaphragm surfaces without CP at same time CP system is applied (\$802,500) (**PLANNED**)
- Replace zinc and aluminum alloy CP systems at lower substructure elements with new zinc alloy CP system at the same time CP system is applied to beams and pile caps (\$4,587,500) (**PLANNED**)

Life Assessment Summary and Rehabilitation Successes

- The three options presented provides TxDOT a pathway for the QIC to systematically achieve an estimated service life of an additional 70 years (1973 to 2043)
- Controlling bridge elements are the pre-stressed beam and substructure elements
- The QIC is in good condition considering its age and service environment

Things to Consider

- TxDOT has committed to Option 3 to sustain serviceability to year 2043 and beyond
- Steel unit will receive its fourth paint system and a closer investigation with respect to nominal thicknesses need to be evaluated beyond further painting systems
- Re-application of the cathodic protection will need to be done but further investigation needs to be considered for the concrete beams
- A Life Cycle Cost will need to be performed beyond 2043 to evaluate a replacement benefit cost ratio. For now, it makes financial sense to maintain the QIC.
- Routine Maintenance efforts are still required to sustain predicted service life estimate. Routine Maintenance efforts planned in FY 19 ~ \$ 1 M.
- Pharr District understands the need for routine maintenance efforts and to address the right treatment at the right time before the treatment scope turns into replacement efforts. TxDOT's maintenance efforts are reflective in the Service Life Assessment performed in 2009. The report serves as a guide for the QIC to reach and possibly exceed the estimated service life beyond in 2043.

QIC 2013 Repairs Rehabilitation Efforts

Exposed Pre-Stressed Strand – Corrosion Propagating



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER


Completed Concrete Structure Repairs (Beam)



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Armor Joint Plate – Deformation



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Armor Joint Repair

Removal and Replacement of Armor Joint



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Beam End at Various Locations Deteriorated Epoxy Coating and Exposed/Corroded Strands



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Beam Ends with Epoxy Coating



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Existing Rail Connection – Typical Existing Anchor Bolts and Hardware Severely Corroded



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Completed Bridge Rail Retrofit with SAP Seal Covers



NATIONAL BRIDGE PRESERVATION PARTNERSHIP CONFERENCE 2018

PRACTICES WE CAN NOT AFFORD TO DEFER

Successful Implementation of Steel Coating and Bridge Rehabilitation

Tribute to our past engineers for having the foresight not to push design limits in a corrosive environment. Such simple implements include the following:

- 80' Simple Spans – this is the practical and economical limit for a Type 54 Beam use. The ultimate design limit could reach up to 110' thus placing more stress and strain on the beams and pre-stressing strands.
- Concrete Diaphragms – no longer used in TxDOT bridge design, the internal diaphragms help distribute live and dead loads acting on the beams. Without placement at the quarter points, would place additional stress and strain on the beams.
- Pre-stressed Pre-Cast Concrete Panels – a new concept of TxDOT bridge design at that time. The 4" deep concrete panels act as a forming mechanism with the remaining 4" of batch concrete placed to make the 8" deep slab. Little to no chance of corrosive sulfate penetrating into the steel which would lead to deck repair.

Reasons for QIC in Good Condition

- Multi-column Bents w/Tie Beams – the use of tie beams at mid height of the column and at the top of the pile footing caps help with load distribution, slenderness, and limiting cracks along the columns
- Cathodic Protection – the implementation of cathodic protection has prevented the substructure elements (steel reinforcement) from being compromised in a corrosive environment. Re-application of the sacrificial layer is needed to sustain the primary function of the bridge element.

TxDOT's Plan Moving Forward

- The steel girder will be stripped and painted a fifth time ~ 2020+. Concerns with reducing nominal thicknesses and tears in the welds.
- Cathodic protection could be applied to the substructures and girders
- Life cycle cost needs to be investigated for continual maintenance remedies beyond 2043
- TxDOT plans to keep the QIC in good condition with strategic and time based maintenance efforts to prevent load posting and continue to serve as a life line to the traveling public and adjacent stakeholders

QUESTIONS?

Rex A. Costley, P.E.
Texas Department of Transportation
Director of Maintenance

Rex.Costley@txdot.gov
(956) 702-6137