

Investigations of Fractures in Three Kentucky Transportation Cabinet Steel Bridges

Theodore Hopwood II P.E.
Kentucky Transportation Center
NEBPP Annual Conference
September 9, 2019



I-75 NB Bridge Over Lynn Camp Creek in Whitley County KY


- Built in 1966 (SB & NB twin bridges)
- Continuous welded steel girder structure with 4 girder lines
 - 140'-200'-140' spans
 - 84" deep girders (webs)
- Made from ASTM A36 steel
- Traffic count over bridge 18,000 vehicles
- Fractures in center span of both bridges in 2012
- Fracture in center span of NB bridge in 2014

Girder Cracking in NB & SB Bridges in 2012




IDOT Circular Letter 2010-09

$\frac{1}{4}$ " or greater separation between welds in web gap




There may or may not be a weld present connecting the wind bracing connection R and vertical stiffener

Wind bracing connection R 's with $\frac{1}{4}$ " or greater clear gap between welds has a low risk of constraint-induced fracture.



Longitudinal stiffener terminations in areas of the web subject to tension are vulnerable to constraint-induced fracture if there is insufficient weld clearance.

$\frac{1}{4}$ " or greater separation between welds in web gap




Longitudinal stiffener terminations with $\frac{1}{4}$ " or greater clear gap between welds present a low risk for constraint-induced fracture.



Cracking in N.B. Bridge June 2014





Fracture Surface Analysis



Fracture Origin



Fracture Details



Investigation findings

- Girder experienced unstable brittle fracture in the web
 - Unstable fracture initiated by a 5mm x 1 mm fatigue crack
- Web base metal was found to:
 - Meet the physical & mechanical properties met the ASTM A36 “Carbon Structural Steel” Standard
 - Satisfy the requirements for Charpy V-Notch toughness for Zone II (non-fracture critical structures)
 - 15 ft-lb. @ 40° F
- Fracture mechanism - possible CIF/fatigue interaction causing unstable fracture
 - Small fatigue crack at horizontal stiffener termination (Cat E fatigue detail)
 - Interaction with CIF detail (vertical & horizontal fillet welds for lateral bracing attachment in girder webs)
- At time of repair, the crack in the lower flange and was growing by fatigue

Bush Road over I-24 Trigg County KY


- Built in 1978
- Continuous welded steel girder structure with 4 girder lines
 - 97'-121'-97' spans
 - 60" deep girders
- Made from ASTM A36 steel
- Traffic count over bridge ??
- Twin cracks were detected a on fascia girder in 2016
 - Negative moment area at pier

Bush Road Bridge & Fracture Location




Fractures in Horizontal Stiffener


Upper Stiffener




Lower Stiffener



SEM Pictures of Fatigue Crack Surfaces



Upper Horizontal Stiffener



Lower Horizontal Stiffener

Lateral Displacement of Web Fracture Surfaces



Investigation findings

- Girder experienced unstable brittle fractures in the web
 - Fractures were initiated by two 5mm x 1 mm fatigue cracks
- Web base metal was found to:
 - Meet the physical & mechanical properties met the ASTM A36 “Carbon Structural Steel” Standard
 - Satisfy the requirements for Charpy V-Notch toughness for Zone II (non-fracture critical structures)
 - 15 ft-lb. @ 40° F
- Category E fatigue details at horizontal stiffener termini
 - No constraint present
- Fractures caused by low-cycle fatigue
 - Due to periodic heavy farm-to-grain elevator farm loads
 - Girder presumed to be highly stressed at time of failure

KY 259 over Rough River

- Built in 1960
- Continuous welded steel girder structure with 4 girder lines
 - 120'-170'-120' spans
 - 78" deep girders (webs)
- Made from ASTM A373 steel
- Traffic count over bridge 1,800 vehicles
 - 6.6 percent trucks
- 2018 fracture on interior girder
 - Found by boater

Girder Fracture

- Girder #3
 - 14' from C.L of 170' span
 - Located in lower flange weld
 - 1-1/8" to 1-3/8" thick transition
- Fracture
 - Lower flange 100%
 - Web 100%
 - Upper flange (~ 5% + arrest)





Crack Surface Observation



Thumbnail Crack Feature

- Located at flange transition butt-weld adjacent to web-to-flange welds
- Appears to be semi-circular or elliptical
 - From ruled scale in picture, the feature appears to be $\approx 3/4$ " wide x $\approx 3/8$ " deep
- Surface texture doesn't match balance of the fracture surface
 - Smooth vs. granular & irregular
 - Possible concentric "beach marks" indicating a fatigue crack

AASHTO S-N Diagram for Steel Bridge Details



Calculation of Initial Defect Size

$$(1) K_{lmax} = 1.12 M_k \sigma (\pi \alpha)^{0.5}$$

$$(2) \, da/dN = 3.6 \times 10^{-10} (\Delta K_I)^3$$

$$(3) N = 1/\Delta\sigma (3.6 \times 10^{-10}) [(1.12) (\pi)^{0.5}]^3 (-\frac{1}{2} \alpha_i^{-0.5} + \frac{1}{2} \alpha_f^{-0.5})$$

Solving for α_i = initial crack depth where:

N = 1.56×10^6 stress cycles

α_f = final crack size= 0.375"

Case 1 $S_r = \Delta\sigma = 3.0 \text{ ksi}$
 $\alpha_i \approx 0.35''$

Case 2 $S_r = \Delta\sigma = 6.0 \text{ ksi}$
 $\alpha_i \approx 0.23''$

Investigation findings

- Girder experienced unstable brittle fracture
 - Initiated at a defect in the lower flange butt weld or flange-to-web fillet weld
- Web base metal was found to:
 - Meet the physical & mechanical properties met the ASTM A373 “Structural Steel for Welding” Standard
 - Satisfy the requirements for Charpy V-Notch toughness for Zone II (non-fracture critical structures)
 - 15 ft-lb. @ 40° F
- Number of stress cycles and equivalent stress range too low to cause fatigue initiation at weld details
 - Possible weld defect missed by QC & QA (shop NDE)
 - Gradual crack growth by fatigue to critical size for unstable brittle fracture

Differing Factors in the Bridge Fractures

- Traffic volumes
- Loading
- Cause of fractures
 - ClF as a contributing factor only on I-75 bridge
 - Weld details (Category E) only in two cases
 - Weld defect only in one case

Common Factors in the Bridge Fractures

- Bridge type - continuous steel girder
 - Redundant 3-spans with 4-girder lines
- Welded construction
- Service lives (40-60 years)
- Use of carbon structural steels
 - All met ASTM & AASHTO requirements
 - Similar to Hoan Bridge
- Small crack sizes able to initiate unstable brittle fractures

Implications

- The critical crack sizes in carbon steel bridge members were too small to be reliably detected visually
 - Even using arms-length inspections
 - NDE is needed
 - The only current safeguard using visual inspection is structural redundancy
- Girder fractures incur costs
 - Reactive maintenance
 - Motorist delays
- Potential risk of collapse
- Other actions are needed to prevent further incidents
 - Bridges with FCMs, fatigue-prone and/or CIF details are primary concerns

Proactive Steps to Address the Situation

- 859 steel Cabinet-owned bridges were built between 1955 and 2000
 - Average age – 46 years
 - Possible welded construction (begun in 1955)
 - Primarily made from carbon steels - ASTM A7, A373 & A36 (ended in 2000)
- KTC is identifying bridges with CIF details for the Cabinet
 - Past work by KTC in identifying QT and problematic HSLA steels
- Arm-length inspections could prove inadequate in some cases
 - That situation needs to be addressed
- Anticipate future work to identify fatigue-prone weld details
 - AASHTO fatigue categories E, E' and F
- Hidden weld defects?
- Some prioritization will be needed to focus future work

The End

Theodore Hopwood II P.E.
Kentucky Transportation Center
NEBPP Annual Conference
September 9, 2019

