



Replacement of Non-Redundant TPG Cover Plates



NHDOT Bridge Maintenance
Andrew Hall, PE




Distance from bearing to bearing = 70'
Width from curb to curb = 24'



Results of the bridge inspection


Lower Flange Deterioration



SECTION OF LOWER FLANGE

N.T.S.

THIS CONDITION OBSERVED AT LOCATIONS NEAR MIDSPAN, AT FB LOCATIONS,



SECTION OF LOWER FLANGE

N.T.S.

* THIS CONDITION OBSERVED AT SEVERAL LOCATIONS (SOUTH GIRDER @ FB#4, FB#10, N. GIRDER @ FB#4)

THIS LOCATION GOVERNS, 17.5' OUT FROM ABUT.



Typical condition of existing cover plate



Lower flange section loss in critical area



Proposed Repair

- Reinforce lower flange by removing 7/16" x 14" x 30' cover plate and replacing 3/4" x 14" x 50' cover plate

Challenge

- How can we support the bridge?

NHDOT keeps on hand a selection of salvaged bridge girders for emergency use






Ideas

Support Detail

Support Girders

Through Plate Girder



Floor beam

Cover Plate

Deleading from raft





New cover plate was fabricated and heat straightened. Heat straightening reduced the "warp" from $1 \frac{5}{16}$ " to $\frac{5}{8}$ ".



Bearing for support girders



Placing support girders



Support girders in place



The tops of the support girders did not line up.



Jacking apparatus in place



Jacking system at floorbeam



Jacking in progress

Then it started raining...



...and raining...



... and raining until the bridge almost became an island.





Using the existing cover plate as a pattern



Drilling holes



Tensioning bolts



Completed Repair!