

Oregon's Approach to Timber Pile Repair

2016 WBPP Annual Conference

By: Travis Kinney, P.E.

Overview


- Background on timber pile inventory.
- Previous pile repair standard.
- Development and field installation.
- Destructive Testing




Timber Pile Inventory

- Oregon has 874 bridges with exposed timber piling.
 - 296 are state owned.
 - 578 are local agency.
- Most were constructed between the 1950's and 1980's, but the range goes from 1906 to 1996.
- Local agency bridges account for the majority of these built during the 1970's and 1980s.

Oregon Timber Pile Inventory



Oregon Timber Pile Inventory



Annual Timber Repair Costs

- Over the last 5 years (2012-2016):
 - 100 Major Bridge Maintenance Projects
 - Total Cost of \$4.3 Million
 - Accounts for 10% of major bridge maintenance budget

Timber Substructure Inventory

- South Yamhill Bridge
- Built in 1951
- Located in Willamette Valley
- Reinforced Concrete Deck Girder on Timber Pile Trestles.
- 990 ft. in length
- 34 Timber Bents
- 204 timber piles (As constructed)
- Estimated cost of replacement = \$35 Million

Replacing bridges 1-piece at a time

- 85 of the original 204 timber piles have been repaired.
- The remaining 119 are just waiting their turn.




Previous Standard Pile Repair

- Splice new steel H-Pile to existing timber with reinforced concrete collar.
- Standard detail provided in 1983.
- Make splice at 100% solid timber section.
- Concrete splice has a 30" diameter and is 4' in length.
- Uses 10 #6 reinforcing bars w/ #5 hoops @ 6" spacing.

OREGON DEPARTMENT OF TRANSPORTATION

Timber Pile - Steel Splice Repair (7/18/83)





Drawbacks

- Difficult to install in tight spaces (abutments)
- Required excavation to continue at least 2' deeper than rot.
- Typical excavation = 2.5 cu. yd.
- If rot extended more than 2' below ground level then shoring or benching excavation was required.
- 18 cu. ft. of concrete for splice (2,700 lbs.)
- Steel cage difficult to stage.



New Pile Repair Wish List

- Avoid the reinforced concrete splice.
- Reduce the required splice length.
- Reduce depth of excavation. (Splice at a section with less than 100% solid timber x-section).
- Use hydraulic jack to preload the pile instead the screw jacks.

Proposed Pile Repair Method

- Replace reinforced concrete collar with oversized steel pipe pile grouted to timber pile.
- Allow splice at a location with less than 100% solid timber section.
- Auger out remaining rotten timber pile core and fill cavity with high early strength concrete.
- Splice steel pipe pile to square structural steel tubing.
- Replace screw jacks with hydraulic jack and field welded shims.

Step 1: Install shoring as required by jacking plan



Step 2: Excavate 2' below Ground Line



Step 3: Cut out section of rotted pile



Step 4: Remove remaining rotten core






04/13/2015

2015 WBPP Annual Meeting

Step 5: Install borate rods



Step 6: Fill cavity with high early strength concrete.



Step 7: Weld cover plate in place



Step 8: Use
vent holes
to finish
pour



Step 9: Preload with 20 ton hydraulic jack




Step 10: Cut shims to fit and weld in place



Step 11: Back fill to existing ground level



Pile Repair Plan Details



SECTION A-A

Scale: 3" = 1'-0"

How much rot is too much to repair?




Timber Pile Splice Testing

- ODOT contracted with Oregon State University to destructively test pile splice detail.
- 6 piles in total were tested; 3 flexure and 3 compression.
- Rot was simulated to varying depths:
 - 21”
 - 35”
 - 49”



Timber Pile Splice Testing



DATE	REVISION	BY	DESIGNED
			Troya Kinney

ACCOMPANIED BY DWGS. See sheet 1 for this structure.

2016.WBPP.A General Meeting

OREGON DEPARTMENT OF TRANSPORTATION

BRIDGE ENGINEERING HEADQUARTERS
 4040 Palouse Island
 Salem, OR 97302-1142
 (503) 586-4200

STRUCTURE NO. Std. Detail
DATE March 7, 2015
CALC. BOOK

TIMBER PILE REPAIR
 STEEL SPLICE DETAIL TESTING

TEST PILE DETAILS

SHEET 7 OF 11
DRAWING NO. 00000

THIS IS THE FILENAME LOCATION *****

DD-MMM-YYYY HH:MM USERNAME

Rotation: 0° Scale: 1 1/2"=1'-0"

14" dia. piles previously in-service



Removed material to leave 2" solid shell.



When auger isn't deep enough...







04/13/2015

2015 WBPP Annual Meeting


Compression Test Piles

- 13"-14" diameter.
- Core removed leaving 2" shell.
- 8' in length.
- Steel pipe pile Circular HSS 16"x 3/8" (ASTM A500 Gr B)
- Testing cross-sectional capacity and localized failures around splice.
- Predicted failure mode: localized buckling in unconfined timber shell.

Compression Test Setup



Compression Test Setup





06/01/2015




Compression Test Results:

- 150 TON (300,000 lbs) actuator was not sufficient to fail any of the test specimens.
- An effect of concrete plug length could not be discerned.


Table 3.1: Compression test summary

Test Specimen #	Length of concrete plug (in)	Stiffness (Kip/in/in)	load at non-linear (Kip)
1	21	450	N/A
2	35	90	250
3	49	93	240

Lateral Test Setup



Lateral Test Setup





06/04/2015

Bending Test Results

- All three failed at the base of the splice.
- Failure loading consistent with anticipated capacity of un-repaired pile.
- Ductile failure ($>12''$ of deflection at pile end)

Table 3.2: Summary of bending test results

File No.	Depth of concrete (in)	Maximum load (lbf)	Apparent Stiffness (lbf/in)	Moment induced at the failure section (kip.ft)
4	21	12233	3077	122
5	35	11217	2863	112
6	49	4843	1060	49

Conclusion

- Proposed pile repair can be used to fully restore axial capacity for short columns.
- Lateral demand and remaining capacity should be evaluated as part of repair plan.
- Provide additional lateral support as required.

Questions?

Contact Information:

Travis Kinney, PE

Oregon Department of Transportation

Major Bridge Maintenance Engineer

Email: Travis.J.Kinney@ODOT.State.OR.US

Phone: 503-986-4010