WELL TIMED BRIDGE PRESERVATION


2016 Midwest Bridge Preservation Partnership
Annual Meeting






Mark Traynowicz
October 4, 2016

FHWA – Bridge Preservation Guide



FHWA – Bridge Preservation Guide

Preventive Maintenance



Nebraska Preservation

- Design with preservation in mind
- Jointless bridges
- Deck protection on good decks

- Old way of doing business
- New ideas

One Deck for Life

ONE DECK FOR LIFE

Re-decking NU Girders will be challenging




CASE STUDY

SL51A00068 – Brule, NE over Platte River Built – 1934 Widened/Lengthened – 1974



CASE STUDY

SL51A00068 – Brule, NE over Platte River Built – 1934 Widened/Lengthened – 1974



CASE STUDY

SL51A00068 – Brule, NE over Platte River Built – 1934 Widened/Lengthened – 1974



CASE STUDY

SL51A00068 – Brule, NE over Platte River Built – 1934 Widened/Lengthened – 1974

Only deck area deteriorated is along the deck edge



CASE STUDY

SL51A00068 – Brule, NE over Platte River Built – 1934 Widened/Lengthened – 1974

Original Deck Region



CASE STUDY


SL51A00068 – Brule, NE over Platte River Built – 1934 Widened/Lengthened – 1974

Widened Deck Region



ONE DECK FOR LIFE


• 1970's - 26 bridges built with Fabric Membrane



__HALF__CROSS ___ SECTION___ Scale 1/2"

ONE DECK FOR LIFE

• 1970's – 26 bridges built with Fabric Membrane



Deck Overlays - EPO



Deck Overlays – Fabric Membrane, Option 1





Deck Overlays – Fabric Membrane, Option 2 2-ply fabric w/ PG Binder



Deck Overlays – Liquid Membrane





Deck Overlays – Asphalt Placement





Joints – Asphalt Plug










Joints – Polymer Nosing











Deck Overlays – Membrane Candidate



Deck Overlays – Membrane Candidate



Tining Depth Gage – Determine Extent of Deck Prep.



Preservation – Joints and Bearings

Joints





Preservation – Joints and Bearings

Joints





Preservation – Joints and Bearings

Joints





Preservation – Joints and Bearings Joints



Joints – Started collecting Element Data in 2014

	Condition States			
	1	2	3	4
Defects	GOOD	FAIR	POOR	SEVERE
Leakage (2310)	None.	Minimal. Minor dripping through the joint.	Moderate. More than a drip and less than free flow of water.	Free flow of water through the joint.
Seal Adhesion (2320)	Fully adhered.	Adhered for more than 50% of the joint height.	Adhered 50% or less of joint height but still some adhesion.	Complete loss of adhesion.
Seal Damage (2330)	None.	Seal abrasion without punctures.	Punctured or ripped or partially pulled out.	Punctured completely through, pulled out, or missing.
Seal Cracking (2340)	None.	Surface crack.	Crack that partially penetrates the seal.	Crack that fully penetrates the seal.
	*			

Paint Bearings







Turndowns & Approaches





Preservation - Piling

Piles





Preservation - Piling

Piles







ONE DECK FOR LIFE

• Membrane on New Bridges



Questions?

