



CONCRETE METALIZING ON THE QUEEN ISABELLA CAUSEWAY

Steven Austin

Texas Department of Transportation




Table of contents

- 1 What is Concrete Metalizing?
- 2 Queen Isabella Causeway
- 3 History of Concrete Metallizing on Queen Isabella Causeway
- 4 Recent Condition Survey for Preservation
- 5 Summary of Findings and Path Forward


What is Concrete Metalizing?

- Applying a metallic coating to provide increased protection to corrosion of reinforcing through cathodic protection.
- Usually applied in salt-rich environments.
- FHWA research has shown that metalizing can outperform many other coatings.
- Some resources suggest a +25 year life for metalized coatings.
- In marine environments these systems may have a reduced service life.
- Metalizing can be effective with passive system or impressed current system.

What is Concrete Metalizing?



Queen Isabella Causeway



Queen Isabella Causeway

- 12,521' Long Bridge Constructed in 1974
- 147 - 80' simple P.S. concrete beam approach spans
- 3 span – 750' Continuous Steel Plate Girder Unit
- 67.75' overall width
- Bridge has had several preservation type projects



Table of contents

- 1** What is Concrete Metalizing?
- 2** Queen Isabella Causeway
- 3** History of Concrete Metallizing on Queen Isabella Causeway
- 4** Recent Condition Survey for Preservation
- 5** Summary of Findings and Path Forward

1996 Demonstration Project

- FHWA/TxDOT Demonstration Project
 - Bent 19 – Thermally sprayed zinc anode with impressed current - anticipated to have a 12 yr life
 - Bent 20 – Thermally sprayed titanium anode with impressed current – anticipated to have a 40 yr life
 - Bent 21 – Titanium mesh concrete overlay
 - Bent 22 – Thermally sprayed zinc anode without impressed current




1996 Demonstration Project

- Cover meter readings indicated cover over 3.5"
- Various crack widths from 0.03" to 0.125".
- No delaminations identified



1996 Demonstration Project

- Half-cell potential readings correlated well with cracks.
- Moderate to very high chloride content at reinforcing level.
- Application of metalizing to splash zone only



Notes:

First number represents bent location where chlorides were taken

Letter next to first number is the sample identification for a given bent

Number in parentheses are the chloride contents at the level of the reinforcing steel expressed in lb/yd³



1996 Demonstration Project

- Project Findings:
 - The two systems with the highest service life costs showed premature deterioration in the performance evaluation
 - Sprayed zinc provided the highest productivity of installation
 - Sprayed zinc provided the most economical option




2004 & 2005 Cathodic Protection Projects

- 2004 Metalizing
 - Zinc coating – 15 mils applied to 72 bents
 - Aluminum (Al-Zn-In) – 12 mils applied to 14 bents
- 2005 Metalizing
 - Zinc coating to remainder of 57 bents with pile caps



2004 & 2005 Cathodic Protection Projects

- 2004 Jackets with Bulk Anodes Bents 1 to 7 and 140 to 151



- Assessment to determine effectiveness and remaining life of bridge
- Cathodic protection was effective
- More rapid average consumption of the Al coating compared to the Zn coating
- Recommended re-application to the aluminum-coated bents




- More rapid consumption of the anode at the connection to reinforcing. Loss of this connection could result in loss of effectiveness
- 5 years after installation assessment estimated service life of metalizing protection of 10 to 15 years of service life.



2011 Metalizing

- Removed Aluminum alloy metalizing previously applied at some bents and replaced with Zinc coating
- Installed new anode connector plates at nearly all other locations



- Found Zn metalizing of 2004/2005 to be completely consumed at some locations.
- 2011 TSZ had nearly twice as much coating blistering as did the 2004/2005
- Half of the 2004/2005 bents tested showed ineffective cathodic protection based on Polarization Testing and Half-Cell potential.



- Recommended re-application of metalizing at \$9.5M to provide service life of 20+ years



- TxDOT review
 - Extensive literature research on metalizing and corrosion evaluation and mitigation plans
 - June 20 and 21, 2018 field trip by TxDOT employees using resistivity meters and coating sampling.
 - Visual assessment confirmed areas of no remaining metalizing at various locations
 - Approaching end of useful coating life after 7 years at locations coincident with what appears to be poor construction quality (honeycombing).

- TxDOT review
 - Resistivity readings of 11-70 k Ω -CM in many footings.
 - Some top of footing readings were in the single digits.
 - Corrosion is active
 - 2011 application is also approaching the end of the useful life



- TxDOT review
 - The use of bulk zinc anode for Bents 1 to 7 and 140 to 151 appears to be quite effective
 - The cathodic protection at these bents is still effective with protection extending into the bent caps.



Summary of Findings and Recommendations

- Performance is not as effective as anticipated likely due to splash zones contributing to quicker consumption of metal coating.
- Life expectancy of TSZ is greater than TSA.
- 15 year life may be achieved but in the case of QIC, new anode connector plates were required after 6 or 7 years.
- Not as effective at mitigating corrosion under conditions of poor construction quality
- Second application is not as effective due to more loss of surface mortar removed during surface preparation.




Summary of Findings and Recommendations

- To address poor construction quality issues in splash environments, consider GFRP jackets with buried zinc anodes in lieu of concrete metalizing.
- To provide protection against corrosion in coastal splash environments, install submerged bulk zinc anodes after performing concrete repairs in lieu of metal coating.



Summary of Findings and Recommendations

- Submerged Zn bulk anodes appear to be a low cost, technically viable option for corrosion control on substructures of the type investigated
- Include monitoring system to ensure the proposed system is working.
- Estimate \$3M for installation and monitoring system on all pile caps.



Copyright 2019 • Texas Department of Transportation • All Rights Reserved Entities or individuals that copy and present state agency information must identify the source of the content, including the date the content was copied. Entities or individuals that copy and present state agency information on their websites must accompany that information with a statement that neither the entity or individual nor the information, as it is presented on its website, is endorsed by the State of Texas or any state agency. To protect the intellectual property of state agencies, copied information must reflect the copyright, trademark, service mark, or other intellectual property rights of the state agency whose protected information is being used by the entity or individual. Entities or individuals may not copy, reproduce, distribute, publish, or transmit, in any way this content for commercial purposes. This presentation is distributed without profit and is being made available solely for educational purposes. The use of any copyrighted material included in this presentation is intended to be a “fair use” of such material as provided for in Title 17 U.S.C. Section 107 of the US Copyright Law.