

Washington State Polyester Concrete Activity

**Andre' La Foe
Bridge Deck Program Manager**

Polyester Concrete Overlays



Polyester Concrete – Material Characteristics




	³ / ₄ " Polyester	1.5" Mod Concrete
Compressive Strength, psi	6,000	7,000+
Flexural Strength, psi	1,500-2,000	0 - 500
Wear	3/8" / 25yrs	NA
Cure Time (3,000psi)	3-4 hr	42 hr
Chloride permeability	0	300 - 700

Polyester Concrete - Weather Restrictions

- Temperatures above 50 (> 60 preferred)
- Deck Temp less than 80 deg?
- Dry (no rain for 24 hours)
- Wind not a factor

Asset Management - Deck Deterioration Curve



Asset Management - Decks Beyond 2% Deterioration



Level of effort/expense for repairs is increased

- High risk for full depth repairs
- High risk for extended traffic closures
- Full depth repairs require formwork



Asset Management - Selection Determination


WSDOT Bridge Asset Management Form - Bridges in "Poor" condition

Bridge Number: 0007141B 5 / 720W	Bridge Name: SAMISH RIVER	Milepost: 234.04	County: Skaqit Region: Northwest
Year Built / YR Widened: 1963	Bridge Type: CS	Number of Main/Appr span: 5 / 0	Overall Bridge Condition: Poor
Bridge Width (curb-curb): 33.5 ft.	Bridge Length: 187 ft.	Max Span: 48 ft.	Bridge Deck View  <p>D:\Deck Views\NW Region\005_720W.jpg</p>
Average Daily Traffic: 22,561	Truck%: 14%	Number of Lanes: 2	
Vertical Clearance: NA	Detour Length (miles): 2	Deck Thickness: 18.5 in.	Bridge Profile View  <p>D:\Profile Views\NW Region\005_720W.jpg</p>
Design Load: HS 20	Load Restricted Bridge? <input type="checkbox"/>		
Pin Number: 100578B	CPMS Ad Date: 11/12/2019	Project Name: I-5/SB Samish River - Bridge Deck Overlay	
Bridge Inspection Information			
Date Inspected: 5/23/2018	Superstr Code: 6	Deck Code: 4	
	Substr Code: 7	Scour: 8	
Year "POOR" 2010	Year "POOR" fixed	Year "POOR" Projected	
Problem	Conc Deck Deterioration		
Cure	Deck Repair and Overlay		
Status	Prioritized for Bridge Rehabilitation		
Preservation Cost\$:	\$1,500,000		
<p>This bridge is classified in "POOR" condition due to the NBI DECK CODE.</p> <p>The 2014 bridge inspection noted 187 SF of deck patching (3.3%). The NBI deck code is a "4" based on the deck patching exceeding 2%.</p> <p>The original concrete slab thickness is 18.5 inches with 1.5 inches of concrete cover over the top mat of deck reinforcing.</p> <p>A future bridge deck rehabilitation project will shotblast 1/2 inch from the existing slab, perform deck repair and apply a 3/4" polyester overlay.</p>			

Polyester Concrete Overlays



Washington State's Concrete Bridge Deck Program



Cost of Bridge Deck Options

Epoxy Rebar -	\$1/SF
ACP w/membr -	\$20/SF
Conc Overlay -	\$80/SF
Polyester Overlay -	\$120/SF
Replace Deck -	\$300/SF
Replace Bridge -	\$1000/SF

Polyester Concrete - History Summary



Polyester Overlays from 1989 to 1999



SR-18 Holder Creek Bridge



- **Built: 1961**
- **Polyester applied: 1989**
- **ADT: 9722**

SR-18 Holder Creek Bridge



- Deck condition after 10 years.
- Under contract for rehab.

Polyester Overlays since 2000



14 Bridges = 504,168 SF

Polyester Overlays – Next Up



15 SB. Toutle R: 2019



SB I-5 Toutle River Bridge – Deck Rehab



- Bridge Built – 1969
- ADT – 22,511

Deck – Looking North

BMS Elements							
Element	Element Description	Total	Units	CS 1	CS 2	CS 3	CS 4
12	Concrete Deck	14,832	SF	14,373	450	9	0
35	Concrete Deck Soffit	14,832	SF	14,702	126	4	0




North Joint



South Joint




Deck View



- Thin polymer overlay applied in 1991



BRIDGE PLAN VIEW GPMR COVERAGE MAP



GPMR DECK SCAN NOTES

- SCAN COLLECTION DATE 10/25/18
- CONTROL UNIT SIR30 HIGH SPEED MULTI CHANNEL RADAR
- ANTENNA ARRAY (3 EACH) 3000 MHZ WIDEBAND HIGH FREQUENCY TRANSDUCERS
- 3D GPMR IMAGE SIZE X= 304.00' Y= 48.00' Z= 12.00"
- DATA PROFILES 2.0' ON CENTER
- (X, Y, Z) ORIGIN IN NE CORNER OF DATA SET/ DECK
- © INDICATES COVER THICKNESS FIELD MEASUREMENT
- BLUE LINES INDICATE DATA GAP BETWEEN MIDDLE & WEST LANES
- GREEN LINES INDICATE PROFILE POSITION




THIS DRAWING, INCLUDING ALL INFORMATION CONTAINED HEREIN, IS THE PROPERTY OF GPR DATA LLC, AND MAY NOT BE USED EXCEPT AS APPROVED BY WRITTEN CONSENT.

GENERAL NOTES: ALL DIMENSIONS ARE ROUNDED TO THE NEAREST 1/16". ALL DIMENSIONS ARE IN FEET AND INCHES EXCEPT AS NOTED. WWW.GPRDATA.COM	REVISED:	GPR Data Inc.—Portland, OR	Cowlitz County WA
	REVISED:	Don Spahr—WASHDOT	Castle Rock (vicinity)
Washington State Department of Transportation	REVISED:	15 SB Toutle River Bridge	GPR DATA JOB#:
	REVISED:	SB MP 51.48—51.98	DD00401
	DRAWN BY:	GPMR Concrete Deck Testing	SHEET 001A
	CHECKED BY:		DATE: 11/18/18



BRIDGE PLAN VIEW AMPLITUDE DETERIORATION MAP



AMPLITUDE (AMP) REBAR LEVEL DETERIORATION INCREASING




GENERAL NOTES: ALL DIMENSIONS ARE ROUNDED TO THE NEAREST 1/16". ALL DIMENSIONS ARE IN FEET AND INCHES EXCEPT AS NOTED. WWW.GPRDATA.COM	REVISED:	GPR Data Inc.—Portland, OR	Cowlitz County WA
	REVISED:	Don Spahr—WASHDOT	Castle Rock (vicinity)
	REVISED:	15 SB Toutle River Bridge	GPR DATA JOB#:
	REVISED:	SB MP 51.48—51.98	DD00401
	DRAWN BY:	GPMR Concrete Deck Testing	SHEET 001C
	CHECKED BY:		DATE: 11/18/18

THIS DRAWING, INCLUDING ALL INFORMATION CONTAINED HEREIN, IS THE PROPERTY OF GPR DATA LLC, AND MAY NOT BE USED EXCEPT AS APPROVED BY WRITTEN CONSENT.





BRIDGE PLAN VIEW HIGHEST DETERIORATION AREA MAP



HIGHEST AMPLITUDE (AMP) DETERIORATION AREAS



10000AMP 13000AMP 16000AMP

PREDICTED DETERIORATION THRESHOLD AMPLITUDE (10KAMP—16KAMP)

- Does not replace the need for the Chain Drag Inspection



GENERAL NOTES: ALL DIMENSIONS ARE ROUNDED TO THE NEAREST 1/16". ALL DIMENSIONS ARE IN FEET AND INCHES EXCEPT AS NOTED. WWW.GPRDATA.COM	REVISED:	GPR Data Inc.—Portland, OR	Cowlitz County WA
	REVISED:	Don Spahr—WASHDOT	Castle Rock (vicinity)
	REVISED:	I5 SB Toutle River Bridge	GPR DATA JOB#:
	REVISED:	SB MP 51.48—51.98	DD00401
THIS DRAWING, INCLUDING ALL INFORMATION CONTAINED HEREIN, IS THE PROPERTY OF GPR DATA LLC, AND MAY NOT BE USED EXCEPT AS APPROVED BY WRITTEN CONSENT.	DRAWN BY:	GPMR Concrete Deck Testing	SHEET 001D
	CHECKED BY:		DATE: 11/18/18

Verify the Clearcover Prior to Surface Removal



- **Damaged reinforcing from milling**

NB I-5 Seattle Viaduct – Deck Rehab



NB I-5 Seattle Viaduct

BMS Elements							
Element	Element Description	Total	Units	CS 1	CS 2	CS 3	CS 4
804	Polyester Concrete Overlay	383,043	SF	382,743	0	300	0



Bridge Built – 1966
Length – 5762'
ADT – 90,000
Polyester applied – 2007


NB I-5 Seattle Viaduct – Original Joint Detail

408

Steel Sliding Plate


Units - LF

This element defines a joint with steel sliding plates. The quantity should equal the length measured along the expansion joint.



> 1,800 LF of sliding plate joints

NB I-5 Seattle Viaduct – Modified Joint Detail



Modified Joint - Surface Condition



SB I-5 Seattle Viaduct – Next Up



SB Deck resurfacing/joint replacement programmed for 2020/21.

Program - Periodic Resurfacing of Polyester Overlays



- Programming for resurfacing is a consideration after approx. 10 yrs. of service life.
- $\frac{3}{4}$ " thickness limits multiple resurfacing passes.

Periodic Resurfacing of Polyester Overlays



- New SR-99 Tunnel Surfacing.

Periodic Resurfacing of Polyester Overlays



- New SR-99 Tunnel Surfacing.

Questions?

