

**Northeast & Mid-Atlantic states
In-Place Recycling
Conference**

**Lower Moreland Township
Montgomery County, PA
Heaton Road CIR**

Heaton Road Pavement Problems

- ❖ Major pavement failure
- ❖ High crown
- ❖ Changing cross slope
- ❖ Curb elevation problems
- ❖ No curb reveal in some areas
- ❖ Low tunnel
- ❖ Industrial Mall must uses Heaton Road


















Wilmington Valley
INDUSTRIAL
CENTER



WILMINGTON VALLEY
INDUSTRIAL CENTER



KURT S. REYER
MUNICIPAL COMPLEX
TOWNSHIP OF JERSEY BORO



