


Kent County, Michigan




Kent County Bridges






Major Bridge Crossings





Three Historic Bridges






Timber Covered Bridge






1994 Restoration





Pine Island Bridge



Built in 1924



2014 Superstructure Restoration







Borroughs Bridge



Built in 1925 / Relocated 1995



2015 Clean & Paint






Bridge Crew 2019



- Vegetation Control
- Deck Sweeping
- Joint Cleaning
- Waterproofing
- Epoxy Deck Seal
- Slope Repair
- Culvert Repair



Joint Cleaning






Waterproofing






Longest County Bridge





Epoxy Deck Seal



3/23/15



Slope Repair






Culvert Lining





Deteriorated Box Beams





Box Beam Replacement





Beam Grouting






Metal Culvert Install





Sink Hole





Concrete Box Culvert Install






Concrete Box Culvert






Park Bridge Before






Park Bridge After





Repurposed Steel Girders





Repurposed Steel Girders





100th Street Substructure





10 Mile/Division Bridge



