

Michigan Department of Transportation Emerging Technology




Falling Weight Deflectometer (FWD) testing

Pavement profiling

 Coring at select locations determined by non- destructive testing results

NB US-23 Test Section Surface Profile showing joint Settlement



WB I-94, CS 82021, Belleville, 27 Ft JRCP; 11 inch Concrete; 4 inches CTB





Mid-panel top down cracking starts after a level of joint



Polyurethane Stabilization as a Preventive Maintenance Strategy

- Experimental polyurethane joint stabilization was done by MDOT at a few joints in 2007
- More experimental stabilization techniques were completed in 2009 to refine the process
- FWD tests were run prior to joint stabilization and shortly after work was completed
- Lower deflections and higher load transfer effectiveness was recorded along the outside edge of pavement after the joint stabilization







FWD testing will be done annually to monitor changes in deflections for US-23 NB Asphalt Stabilized OGDC Polyurethane Joint Treatment

FWD results before and after stabilization

Station Reference	Impa #	act Load lbf	l Test Point	Test Type	Prefoam DO Deflection (mils)	Postfoam DO Deflection (mils)	Percent Change
	202	2	7000 TJT	BJT	8.53		-56%
	202	3	9000 TJT	BJT	10.46		-54%
	202	4	12000 TJT	BJT	13.26		-49%
	202	5	9000 TJT	BJT	10.59		-54%
	203	2	7000 TJT	AJT	8.99		-58%
	203	3	9000 TJT	AJT	11.02		-56%
	203	4	12000 TJT	AJT	13.71		-50%
	203	5	9000 TJT	AJT	11.22	4.95	-56%
	229	2	7000 TJT	BJT	9.73	3.39	-65%
	229	3	9000 TJT	BJT	12.05	4.48	-63%
	229	4	12000 TJT	BJT	15.3	6.14	-60%
	229	5	9000 TJT	BJT	12.49	4.49	-64%
	230	2	7000 TJT	AJT	9.78	3.91	-60%
	230	3	9000 TJT	AJT	11.95	5.06	-58%
	230	4	12000 TJT	AJT	15	7.06	-53%
	230	5	9000 TJT	AJT	12.31	5.12	-58%
	244	2	7000 MID	NA	3.69	10.06	173%
	244	3	9000 MID	NA	4.99		164%
	244	4	12000 MID	NA	6.71	17.51	161%
	244	5	9000 MID	NA	5.03		167%
	256	2	7000 TJT	BJT	6.06		-37%

Conclusions



 FWD and pavement profiling are important tools for predicting pavement distress and planning rigid pavement preventive maintenance

 Polyurethane joint stabilization shows promise as a preventive maintenance strategy for delaying top-down cracking in jointed concrete pavement

Emerging Technology Projects

 One project has been awarded and will be completed in the spring on I-94 near Jackson, MI.

 Another project is in the design phase for construction next year on US-23 near Flint, MI.





Slab jacking on M-6 near Grand Rapids